



OLIPHANT DRINKING WATER SYSTEM  
7 FIDDLEHEAD LANE, SOUTH BRUCE PENINSULA, ON,  
N0H 2T0

## INSPECTION REPORT

System Number: 220007695  
Entity: ONTARIO CLEAN WATER  
AGENCY  
THE CORPORATION OF THE  
TOWN OF SOUTH BRUCE  
PENINSULA

Inspection Start Date: July 20, 2023  
Inspection End Date: August 09, 2023  
Inspected By: Robert Graham  
Badge #: 1667



---

(signature)

## **NON-COMPLIANCE**

This should not be construed as a confirmation of full compliance with all potential applicable legal requirements. These inspection findings are limited to the components and/or activities that were assessed, and the legislative framework(s) that were applied. It remains the responsibility of the owner to ensure compliance with all applicable legislative and regulatory requirements.

If you have any questions related to this inspection, please contact the signed Provincial Officer.

## **RECOMMENDATIONS**

This should not be construed as a confirmation of full conformance with all potential applicable BMPs. These inspection findings are limited to the components and/or activities that were assessed, and the legislative framework(s) that were applied. It remains the responsibility of the owner to ensure compliance with all applicable legislative and regulatory requirements.

If you have any questions related to this inspection, please contact the signed Provincial Officer.

### INSPECTION DETAILS

This section includes all questions that were assessed during the inspection.

**Ministry Program:** DRINKING WATER | **Regulated Activity:** DW Municipal Residential

Question ID	DWMR1001000	Question Type	Information
<b>Legislative Requirement(s):</b> Not Applicable			
<b>Question:</b> What was the scope of this inspection?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> <p>The primary focus of this inspection is to confirm compliance with Ministry of the Environment, Conservation and Parks (MECP) legislation as well as evaluating conformance with ministry drinking water policies and guidelines during the inspection period. The ministry utilizes a comprehensive, multi-barrier approach in the inspection of water systems that focuses on the source, treatment, and distribution components as well as management practices.</p> <p>This drinking water system is subject to the legislative requirements of the Safe Drinking Water Act, 2002 (SDWA) and regulations made therein, including Ontario Regulation 170/03, "Drinking Water Systems" (O. Reg. 170/03). This inspection has been conducted pursuant to Section 81 of the SDWA.</p> <p>This inspection report does not suggest that all applicable legislation and regulations were evaluated. It remains the responsibility of the owner to ensure compliance with all applicable legislative and regulatory requirements.</p> <p>On July 20, 2023, Ministry of the Environment, Conservation and Parks (MECP) Provincial Officer Bob Graham conducted an announced focused inspection of the Oliphant Drinking Water System (DWS). The Oliphant DWS is a Small Municipal Residential DWS owned by the Town of South Bruce Peninsula (Owner) and operated by the Ontario Clean Water Agency (OCWA/Operating Authority/OA). Assistance with the inspection was provided by Senior Operations Manager Leo-Paul Frigault, Process &amp; Compliance Technician Karla Young, Overall Responsible Operator (ORO) James Learn and Operator Cole Hutchinson.</p> <p>At the time of the inspection drinking water was being transported from the Warton Water Treatment Plant to the pumphouse and the Oliphant DWS was operating as a storage reservoir and a re-chlorination station. Previous to the use of a transported water system, in an effort to reduce trihalomethanes (THMs) in the distribution system, the Oliphant water treatment plant switched to chloramination for secondary disinfection. The chloraminated water was stored in the clearwells and was also being used to backwash the filters. It became apparent after the 2010/2011 MECP DWS inspection of the DWS that the use of chloraminated water to backwash the filters was interfering with the disinfection process. As the Owner could not demonstrate that adequate disinfection was being achieved the decision to use transported water from the</p>			

Warton drinking water system was put in place and transported water continues at this time. Ontario Regulation 170/03 Section 5 Exemptions: residential systems gives Oliphant DWS relief from sampling nitrate and nitrite, sodium, fluoride, inorganic and organics while transporting water. During the inspection review period, from August 11, 2022, the day following the last inspection, to the date of inspection on July 20, 2023, there were no Adverse Water Quality Incidents (AWQIs) reported to the MECP Spills Action Centre.

Question ID	DWMR1000000	Question Type	Information
<b>Legislative Requirement(s):</b> Not Applicable			
<b>Question:</b> Does this drinking water system provide primary disinfection?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> This drinking water system provides for both primary and secondary disinfection and distribution of water.  Primary disinfection treatment equipment is installed however it is not in use. The Operating Authority currently re-chlorinates the transported water as needed.			

Question ID	DWMR1007000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   1-2   (1);			
<b>Question:</b> Is the owner maintaining the production well(s) in a manner sufficient to prevent entry into the well of surface water and other foreign materials?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The owner was maintaining the production well(s) in a manner sufficient to prevent entry into the well of surface water and other foreign materials.  At the time of the inspection the production wells were not in use and drinking water was being transported from the Warton Water Treatment Plant to the pumphouse and the Oliphant DWS was operating as a storage reservoir and a re-chlorination station. A visual assessment of the above-ground portions of the well(s) determined that the owner is maintaining the well(s) in a manner sufficient to prevent the entry of surface water and other foreign materials as prescribed in the Wells Regulation and Schedule 1 of O. Reg. 170/03.			

Question ID	DWMR1009000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   31   (1);			

**Question:**

Are measures in place to protect the groundwater and/or GUDI source in accordance with any MDWL and DWWP issued under Part V of the SDWA?

**Compliance Response(s)/Corrective Action(s)/Observation(s):**

Measures were in place to protect the groundwater and/or GUDI source in accordance with the Municipal Drinking Water Licence and Drinking Water Works Permit issued under Part V of the SDWA.

Question ID	DWMR1014000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   31   (1);			
<b>Question:</b> Is there sufficient monitoring of flow as required by the MDWL or DWWP issued under Part V of the SDWA?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> There was sufficient monitoring of flow as required by the Municipal Drinking Water Licence or Drinking Water Works Permit issued under Part V of the SDWA.			
<p>The Municipal Drinking Water Licence (MDWL) for the Oliphant DWS (Licence Number 094-105, Issue Number 5) requires monitoring and recording of flow rate and the daily volume of water conveyed into the treatment system and conveyed into the distribution system. Transported water is currently delivered directly into the clearwell so monitoring of flow rate into the treatment system is not necessary. The operating authority continues to monitor and record flow rate and the daily volume of water conveyed into the distribution system.</p>			

Question ID	DWMR1016000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   31   (1);			
<b>Question:</b> Is the owner in compliance with the conditions associated with maximum flow rate or the rated capacity conditions in the MDWL issued under Part V of the SDWA?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The owner was in compliance with the conditions associated with maximum flow rate or the rated capacity conditions in the Municipal Drinking Water Licence issued under Part V of the SDWA.			
<p>The MDWL for the Oliphant drinking water system requires monitoring and recording of flow rate</p>			

and the daily volume of water conveyed into the treatment system and conveyed into the distribution system.

Transported water is currently delivered directly into the clearwell so monitoring of flow rate into the treatment system is not necessary. The operating authority continues to monitor and record flow rate and the daily volume of water conveyed into the distribution system.

Question ID	DWMR1018000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   31   (1);			
<b>Question:</b> Has the owner ensured that all equipment is installed in accordance with Schedule A and Schedule C of the Drinking Water Works Permit?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The owner had ensured that all equipment was installed in accordance with Schedule A and Schedule C of the Drinking Water Works Permit.			
At the time of inspection the Oliphant DWS was receiving transported water from the Warton DWS. Selected equipment was maintained for operation including the high lift pumps, the reservoir/clearwell, the trim chlorination system, analyzers, SCADA system and the back-up power supply system.			

Question ID	DWMR1024000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   1-2   (2);			
<b>Question:</b> Do records confirm that the water treatment equipment which provides chlorination or chloramination for secondary disinfection purposes was operated as required?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Records confirmed that the water treatment equipment which provides chlorination or chloramination for secondary disinfection purposes was operated so that at all times and all locations in the distribution system the chlorine residual was never less than 0.05 mg/l free or 0.25 mg/l combined.			

Question ID	DWMR1034000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   7-2   (5); SDWA   O. Reg. 170/03   7-2   (6);			
<b>Question:</b>			

Is the secondary disinfectant residual measured as required for the small municipal residential distribution system?

**Compliance Response(s)/Corrective Action(s)/Observation(s):**

The secondary disinfectant residual was measured as required for the small municipal residential distribution system.

Subsection 7-2 (5) of schedule 7, O.Reg.170/03 the owner of a small municipal residential system that provides secondary disinfection and the operating authority for the system shall ensure that at least two distribution samples are taken each week in accordance with subsection (6) and are tested immediately for, (a) free chlorine residual. Records provided by the owner and reviewed during the inspection indicate that the owner complied with these requirements, testing free chlorine residual for secondary disinfection monitoring purposes 2 days each week and at least 48 hours apart.

<b>Question ID</b>	DWMR1035000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   6-5   (1)1-4; SDWA   O. Reg. 170/03   6-5   (1)5-10;			
<b>Question:</b> Are operators examining continuous monitoring test results and are they examining the results within 72 hours of the test?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Operators were examining continuous monitoring test results and they were examining the results within 72 hours of the test.			

<b>Question ID</b>	DWMR1038000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   6-5   (1)1-4;			
<b>Question:</b> Is continuous monitoring equipment that is being utilized to fulfill O. Reg. 170/03 requirements performing tests for the parameters with at least the minimum frequency specified in the Table in Schedule 6 of O. Reg. 170/03 and recording data with the prescribed format?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Continuous monitoring equipment that was being utilized to fulfill O. Reg. 170/03 requirements was performing tests for the parameters with at least the minimum frequency specified in the Table in Schedule 6 of O. Reg. 170/03 and recording data with the prescribed format.			

<b>Question ID</b>	DWMR1037000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b>			



SDWA | O. Reg. 170/03 | 6-5 | (1)1-4; SDWA | O. Reg. 170/03 | 6-5 | (1)5-10; SDWA | O. Reg. 170/03 | 6-5 | (1.1);

**Question:**

Are all continuous monitoring equipment utilized for sampling and testing required by O. Reg. 170/03, or MDWL or DWWP or order, equipped with alarms or shut-off mechanisms that satisfy the standards described in Schedule 6?

**Compliance Response(s)/Corrective Action(s)/Observation(s):**

All continuous monitoring equipment utilized for sampling and testing required by O. Reg. 170/03, or Municipal Drinking Water Licence or Drinking Water Works Permit or order, were equipped with alarms or shut-off mechanisms that satisfy the standards described in Schedule 6.

The distribution water chlorine analyzer has a low, low alarm set point of 0.50 mg/L and a high, high alarm setpoint of 2.0 mg/L, which if triggered notifies operators via an alarm dialer and locks out the high lift pumps. Should the chlorine analyzer read 1.3 mg/L concentration in the clearwell(s) a trim chlorinator is activated to increase chlorine concentration in the clearwell(s).

Question ID	DWMR1040000	Question Type	Legislative
<b>Legislative Requirement(s):</b>			
SDWA   O. Reg. 170/03   6-5   (1)1-4; SDWA   O. Reg. 170/03   6-5   (1)5-10;			
<b>Question:</b>			
Are all continuous analysers calibrated, maintained, and operated, in accordance with the manufacturer's instructions or the regulation?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b>			
All continuous analysers were calibrated, maintained, and operated, in accordance with the manufacturer's instructions or the regulation.			

Question ID	DWMR1108000	Question Type	Legislative
<b>Legislative Requirement(s):</b>			
SDWA   O. Reg. 170/03   6-5   (1)1-4; SDWA   O. Reg. 170/03   6-5   (1)5-10; SDWA   O. Reg. 170/03   6-5   (1.1);			
<b>Question:</b>			
Where continuous monitoring equipment used for the monitoring of free chlorine residual, total chlorine residual, combined chlorine residual or turbidity, required by O. Reg. 170/03, an Order, MDWL, or DWWP issued under Part V, SDWA, has triggered an alarm or an automatic shut-off, did a qualified person respond in a timely manner and take appropriate actions?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b>			
Where required continuous monitoring equipment used for the monitoring of chlorine residual and/or turbidity triggered an alarm or an automatic shut-off, a qualified person responded in a timely manner and took appropriate actions.			

Question ID	DWMR1099000	Question Type	Information
<b>Legislative Requirement(s):</b> Not Applicable			
<b>Question:</b> Do records show that all water sample results taken during the inspection review period did not exceed the values of tables 1, 2 and 3 of the Ontario Drinking Water Quality Standards (O. Reg. 169/03)?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Records showed that all water sample results taken during the inspection review period did not exceed the values of tables 1, 2 and 3 of the Ontario Drinking Water Quality Standards (O. Reg. 169/03).			

Question ID	DWMR1082000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   11-2   (1); SDWA   O. Reg. 170/03   11-2   (2); SDWA   O. Reg. 170/03   11-2   (6);			
<b>Question:</b> For SMR systems, are all microbiological water quality monitoring requirements for distribution samples prescribed by legislation being met?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> All microbiological water quality monitoring requirements prescribed by legislation for distribution samples in a small municipal residential system were being met.  For SMR DWS, distribution bacteriological samples shall be taken: 1) once every 2 weeks provided that the system is in compliance with Schedule 1 of O.Reg. 170/03, or 2) one sample every week if the system does not meet the requirements of Schedule 1 of O. Reg.170/03. Each sample must be tested for EC + TC and, if secondary disinfection is provided, must also be tested for HPC.			

Question ID	DWMR1096000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   6-3   (1);			
<b>Question:</b> Do records confirm that chlorine residual tests are being conducted at the same time and at the			

same location that microbiological samples are obtained?

**Compliance Response(s)/Corrective Action(s)/Observation(s):**

Records confirmed that chlorine residual tests were being conducted at the same time and at the same location that microbiological samples were obtained.

Question ID	DWMR1086000	Question Type	Legislative
<b>Legislative Requirement(s):</b>			
SDWA   O. Reg. 170/03   13-6.1   (1); SDWA   O. Reg. 170/03   13-6.1   (2); SDWA   O. Reg. 170/03   13-6.1   (3); SDWA   O. Reg. 170/03   13-6.1   (4); SDWA   O. Reg. 170/03   13-6.1   (5); SDWA   O. Reg. 170/03   13-6.1   (6);			
<b>Question:</b>			
Are all haloacetic acid water quality monitoring requirements prescribed by legislation conducted within the required frequency and at the required location?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b>			
All haloacetic acid water quality monitoring requirements prescribed by legislation were conducted within the required frequency and at the required location.			
Section 13-6.1 (1) of Schedule 13, O.Reg.170/03 requires the Owner and the Operating Authority to ensure that at least one distribution sample is taken every 3 months from a point in the drinking water system's distribution system that is connected to the drinking water system, that is likely to have an elevated potential for the formation of Haloacetic Acids (HAA), and tested for HAAs. Section 6-1.1 of Schedule 6, O.Reg.170/03 requires that these samples be taken at least 60 days, and not more than 120 days, after a sample was taken for that purpose in the previous three month period. The standard for Haloacetic Acids is 80 ug/L, expressed as a Running Annual Average (RAA), where the RAA is defined as the average for quarterly HAA results for a drinking water system. The required sampling for the inspection period was completed and the RAA results were below the O.Reg. 169/03 standard of 80 ug/L.			

Question ID	DWMR1087000	Question Type	Legislative
<b>Legislative Requirement(s):</b>			
SDWA   O. Reg. 170/03   13-6   (1); SDWA   O. Reg. 170/03   13-6   (2); SDWA   O. Reg. 170/03   13-6   (3); SDWA   O. Reg. 170/03   13-6   (4); SDWA   O. Reg. 170/03   13-6   (5); SDWA   O. Reg. 170/03   13-6   (6);			
<b>Question:</b>			
Have all trihalomethane water quality monitoring requirements prescribed by legislation been conducted within the required frequency and at the required location?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b>			
All trihalomethane water quality monitoring requirements prescribed by legislation were conducted within the required frequency and at the required location.			
Section 13-6 of Schedule 13, O.Reg.170/03 requires the Owner and the Operating Authority to ensure that at least one distribution sample is taken every 3 months from a point in the drinking			

water system's distribution system, or in plumbing that is connected to the drinking water system, that is likely to have an elevated potential for the formation of Trihalomethanes (THMs), and tested for THMs. Section 6-1.1 of Schedule 6, O.Reg.170/03 requires that these samples be taken at least 60 days, and not more than 120 days, after a sample was taken for that purpose in the previous three month period. The standard for THMs is 100 µg/L, expressed as a Running Annual Average (RAA), where the RAA is defined as the average for quarterly THM results for a drinking water system. The required sampling for the inspection time period was completed and the RAA results were below the O.Reg. 169/03 standard of 100 ug/L.

Question ID	DWMR1059000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 128/04   28;			
<b>Question:</b> Do the operations and maintenance manuals contain plans, drawings and process descriptions sufficient for the safe and efficient operation of the system?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The operations and maintenance manuals contained plans, drawings and process descriptions sufficient for the safe and efficient operation of the system.			

Question ID	DWMR1060000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   31   (1);			
<b>Question:</b> Do the operations and maintenance manuals meet the requirements of the DWWP and MDWL issued under Part V of the SDWA?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The operations and maintenance manuals met the requirements of the Drinking Water Works Permit and Municipal Drinking Water Licence issued under Part V of the SDWA.			

Question ID	DWMR1061000	Question Type	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 128/04   27   (1); SDWA   O. Reg. 128/04   27   (2); SDWA   O. Reg. 128/04   27   (3); SDWA   O. Reg. 128/04   27   (4); SDWA   O. Reg. 128/04   27   (5); SDWA   O. Reg. 128/04   27   (6); SDWA   O. Reg. 128/04   27   (7);			
<b>Question:</b> Are logbooks properly maintained and contain the required information?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Logbooks were properly maintained and contained the required information.			

<b>Question ID</b>	DWMR1062000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   7-5;			
<b>Question:</b> Do records or other record keeping mechanisms confirm that operational testing not performed by continuous monitoring equipment is being done by a certified operator, water quality analyst, or person who meets the requirements of O. Reg. 170/03 7-5?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Records or other record keeping mechanisms confirmed that operational testing not performed by continuous monitoring equipment was being done by a certified operator, water quality analyst, or person who suffices the requirements of O. Reg. 170/03 7-5.			

<b>Question ID</b>	DWMR1071000	<b>Question Type</b>	BMP
<b>Legislative Requirement(s):</b> Not Applicable			
<b>Question:</b> Has the owner provided security measures to protect components of the drinking water system?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The owner had provided security measures to protect components of the drinking water system.  The pump house and treatment facility has lockable doors equipped with an intruder alarm. The drilled wells were locked and signage restricts access to the site. At the time of inspection there was no apparent visual evidence of unauthorized access and/or vandalism.			

<b>Question ID</b>	DWMR1073000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 128/04   23   (1);			
<b>Question:</b> Has the overall responsible operator been designated for all subsystems which comprise the drinking water system?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> The overall responsible operator had been designated for each subsystem.  The overall responsible operator for the Oliphant DWS is James Learn, with back-up being provided by Billy Shearer.			

<b>Question ID</b>	DWMR1074000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 128/04   25   (1);			

**Question:**

Have operators-in-charge been designated for all subsystems which comprise the drinking water system?

**Compliance Response(s)/Corrective Action(s)/Observation(s):**

Operators-in-charge had been designated for all subsystems which comprise the drinking water system.

<b>Question ID</b>	DWMR1075000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 128/04   22;			
<b>Question:</b> Do all operators possess the required certification?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> All operators possessed the required certification.			

<b>Question ID</b>	DWMR1076000	<b>Question Type</b>	Legislative
<b>Legislative Requirement(s):</b> SDWA   O. Reg. 170/03   1-2   (2);			
<b>Question:</b> Do only certified operators make adjustments to the treatment equipment?			
<b>Compliance Response(s)/Corrective Action(s)/Observation(s):</b> Only certified operators made adjustments to the treatment equipment.			

Ministry of the Environment, Conservation and Parks - Inspection Summary Rating Record (Reporting Year - 2023-24)

**DWS Name:** OLIPHANT DRINKING WATER SYSTEM  
**DWS Number:** 220007695  
**DWS Owner:** THE CORPORATION OF THE TOWN OF SOUTH BRUCE PENINSULA  
**Municipal Location:** SOUTH BRUCE PENINSULA

**Regulation:** O.REG. 170/03  
**DWS Category:** DW Municipal Residential  
**Type of Inspection:** Focused  
**Inspection Date:** Jul-20-2023  
**Ministry Office:** Owen Sound District Office

**Maximum Risk Rating:** 330

Inspection Module	Non Compliance Risk (X out of Y)
Capacity Assessment	0/30
Certification and Training	0/42
Logbooks	0/18
Operations Manuals	0/28
Reporting & Corrective Actions	0/21
Source	0/14
Treatment Processes	0/126
Water Quality Monitoring	0/51
<b>Overall - Calculated</b>	<b>0/330</b>

**Inspection Risk Rating:** 0.00%

**Final Inspection Rating:** 100.00%

Ministry of the Environment, Conservation and Parks - Detailed Inspection Rating Record (Reporting Year - 2023-24)

**DWS Name:** OLIPHANT DRINKING WATER SYSTEM  
**DWS Number:** 220007695  
**DWS Owner Name:** THE CORPORATION OF THE TOWN OF SOUTH BRUCE PENINSULA  
**Municipal Location:** SOUTH BRUCE PENINSULA

**Regulation:** O.REG. 170/03  
**DWS Category:** DW Municipal Residential  
**Type of Inspection:** Focused  
**Inspection Date:** Jul-20-2023  
**Ministry Office:** Owen Sound District Office

*All legislative requirements were met. No detailed rating scores.*

Maximum Question Rating: 330

Inspection Risk Rating: 0.00%

FINAL INSPECTION RATING: 100.00%