

HURON WOODS WATER TREATMENT PLANT

Small Municipal Residential Drinking Water System

SCHEDULE 22 SUMMARY REPORT

For the period of JANUARY 1, 2014 TO DECEMBER 31, 2014

Prepared by the Ontario Clean Water Agency For The Corporation of the Town of South Bruce Peninsula

SUMMARY

This report is a summary of water quality and quantity information submitted in accordance with Schedule 22 of Ontario's Drinking Water System Regulation for the reporting period of January 1, 2014 to December 31, 2014 for the Huron Woods Water Treatment Plant located in the Town of South Bruce Peninsula.

The summary includes:

- 1. Any requirements of the Act and Regulation, Orders or System Approval (s) that the system failed to meet during the reporting period and the measures taken to correct each failure.
- 2. A summary of the quantities and flow rates of water supplied during the reporting period, including monthly averages and maximum daily flows.
- 3. A comparison of the average and monthly maximum daily flows to the approved capacity specified in the System Approval.

ISSUES OF NON-COMPLIANCE

The following table lists the requirements of the Act, Regulations, System Approval(s) and any Order that the system failed to meet during the reporting period and the measures taken to correct each failure:

Two MOE Inspections were conducted on January 27, 2014 and again on November 25, 2014 which were routine and announced resulting in an Inspection Report Rating 100% each.

No Actions Required.

ASSESSMENT OF FLOW RATES AND QUANTITIES OF WATER SUPPLIED

The following table lists the quantities and flow rates of the water supplied during the reporting period covered by this report, including monthly average and maximum daily flows and a comparison to the rated capacity and flow rates specified in the system approval:

Huron Woods Water Treatment Plant

Month	Average Day Flow	% of Rated Capacity 743 m3/d	Maximum Day Flow	% of Rated Capacity 743 m3/d
January	45.094	6.07	63.5	8.55
February	49.433	6.65	64.2	8.64
March	52.106	7.01	65.1	8.76
April	49.618	6.68	68.5	9.22
May	43.048	5.79	64.9	8.73
June	44.675	6.01	63.3	8.52
July	42.564	5.73	64.1	8.63
August	45.303	6.10	69.1	9.30
September	44.465	5.98	64.9	8.73
October	42.708	5.75	65.1	8.76
November	43.839	5.90	59.8	8.05
December	42.562	5.73	70.6	9.50

Huron Woods Water Supply Works

220007775

Drinking-Water System Number:

Drinking-Water System Name:

Drinking-Water System Owner:	Town of South Bruce Peninsula		
Drinking-Water System Category:	Small Municipal Residential		
Period being reported:	January 1, 2014 to December 31, 2014		
Complete if your Category is Large Mu Residential or Small Municipal Residential Or Small Municipal Residential Or Small Municipal Residential Openation of the Notice of	ntial	Complete for all other Categories. Number of Designated Facilities served:	
Is your annual report available to the no charge on a web site on the Internet Yes [X] No []		Did you provide a copy of your annual report to all Designated Facilities you serve? Yes [] No []	
Location where Summary Report required on the control of the contr		Number of Interested Authorities you report to:	
Town of South Bruce Peninsula 315 George Street Wiarton, Ontario N0H 2T0 519-534-1400		Did you provide a copy of your annual report to all Interested Authorities you report to for each Designated Facility? Yes [] No []	
List Drinking-Water Systems, who	ich receive :	all of their drinking water from your system:	
Did you provide a copy of your an connected to you and to whom you Yes [] No [] N/A [X]		to all Drinking-Water System owners that are l of its drinking water?	
Indicate how you notified system charge.	users that y	our annual report is available, and is free of	
[X] Public access/notice via the we [X] Public access/notice via Gover [] Public access/notice via a news [] Public access/notice via Public [] Public access/notice via a Publ [] Public access/notice via other n	rnment Offi spaper Request ic Library	ce	

Describe your Drinking-Water System

Class Il Water Treatment

Class 1 Water Distribution

The Huron Woods drinking-water system in the Town of South Bruce Peninsula consists of four wells:

- Well No. W1 and old disused Pumphouse
- Well No. W2
- Well No. W3
- Well No. W6 and existing Pumphouse

The Well No. W1 is rated at 1.21 L/s at a TDH of 83.3 m. The Well No. W2 is rated at 0.6 L/s at a TDH of 74.2 m.. The Well No. W3 is rated at 1.51 L/s at a TDH of 105 m and the Well No. W6 is rates at 5.3 L/s at a TDH of 47.6 m.

The existing Pumphouse consists of a Ferrosand Filter system, cartridge filter system, ultraviolet (UV) disinfection system, chlorination system, filter backwash tank, jockey pump, flow control valves (hydraulic), and water meters.

The Ferrosand Filter system consists of two Ferrosand Filter units (one duty, one standby) connected to the common well discharge header, complete with PLC to control backwash cycles, hydropneumatic tank to drive hydropneumatic valves, and all necessary piping and appurtenances. An iron-oxidizing sodium hypochlorite feed system with injection point located prior to the Ferrosand Filter units, consisting of two feed pumps (one duty, one standby) with auto switchover. There are two submersible well pumps (one duty, one standby) each rated at 20.3 L/s at a TDH of 19.5 m for the purpose of backwashing Ferrosand Filter units.

The Cartridge Filter system located after the Ferrosand Filter units has a treatment capacity of 9.55 L/s, equipped with a 5-micron size cartridge.

The UV disinfection system has two UV disinfection reactors (one duty, one standby) located after the cartridge filter unit, capable of providing a minimum dose of 40 mJ/cm2 at end of lamp life and each rated at 9.55 L/s. Each UV reactor has an automatic cleaning system and an on-line UV intensity monitor with alarm.

The Chlorination System has a secondary-chlorination sodium hypochlorite disinfection system with injection point located prior to the treated water entering the reservoir cells, consisting of two metering pumps (one duty, one standby) with auto switchover. There is also a post-chlorination sodium hypochlorite disinfection system with injection point located at the high lift header. It consists of two metering pumps (one duty, one standby) complete with all associated piping and alarms.

The Filter Backwash Tank is one in-ground cast-in-place concrete tank to clarify filter backwash waste with clarified supernatant discharged by gravity to an existing ditch.

The jockey pump is a submersible well pump rated at 5.67 L/s at a TDH of 56 m within Reservoir Cell No. 2.

One of the hydraulic flow control valves is located on the inlet piping from Well No. W1 and Well No. W2 set at 1.21 L/s. Another flow control valve is located in the inlet piping from Well No. W3 set at 1.51 L/s. One flow control valve is located on the inlet piping from Well No. W6 set at 5.3 L/s.

The last flow control valve is located on the combined piping from the two backwash pumps	set at	t 20.3
L/s.		

There are three water meters:

One raw water meter for the raw water header

One total raw water meter located after the common header from all four production wells

On treated water meter prior to treated water exiting the pump house

The 80 kW diesel generator is set with a double-walled sub-base fuel tank with level gauge, low level float switch and leak sensor; all to be housed in the diesel generator building.

The Huron Woods System also contains one programmable logic controller (PLC) and associated SCADA system for control of plant operations.

The last flow control valve is located on the combined piping from the two backwash pumps set at 20.3 L/s.

List all water treatment chemicals used over this reporting period

- Sodium Hypochlorite 12%

Were any significant expenses incurred to?

- [] Install required equipment
- [] Repair required equipment
- [X] Replace required equipment

Describe:

- Replace PALL filtration system filter cartridges
- Replace defective Trojan UV Swift Ballast #1

Provide details on the notices submitted in accordance with subsection 18(1) of the Safe Drinking-Water Act or section 16-4 of Schedule 16 of O.Reg.170/03 and reported to Spills Action Centre

Action Cent	10				
Incident	Parameter	Result	Unit of	Corrective Action	Corrective
Date			Measure		Action Date

Microbiological testing done under Schedule 10, 11 or 12 of Regulation 170/03 during this reporting Period

		Range of	Range of	Number	Range of
	Number	E. Coli or	Total Coliform	of	НРС
	of	Fecal Results	Results	НРС	Results
Location	Samples	(min #) - (max #)	(min #) - (max #)	Samples	(min #) - (max #)
Raw - RW1	13	0 - 0	0 - 0		·
Raw - RW2	13	0 - 0	0 - 0		
Raw - RW3	13	0 - 0	0 - 0		
Raw - RW6	13	0 - 0	0 - 0		
Distribution - DW	52	0 - 0	0 - 0	52	0 - 4

Operational testing done under Schedule 7, 8 or 9 during the period covered by this Annual

Report.

	Number of Grab Samples	Range of Results (#-#)
Turbidity	8760	0.00-0.13
Chlorine	8760	1.11-1.39
Chlorine	111	0.70-1.39
Residual		
Distribution		
System		

NOTE: For continuous monitors use 8760 as the number of samples.

NOTE: Record the unit of measure if it is **not** milligrams per litre.

Summary of additional testing and sampling carried out in accordance with the requirement of an approval or order.

Date of order or C of A	Parameter	Date Sampled	Result	C of A Limit	Unit of Measure
C of A 6008-76YK84	Suspended Solids (composite)	Quarterly	Annual Average < 2.0	25	mg/L

Summary of Inorganic parameters tested during this reporting period or most recent

Parameter	Sample Date		Exceedance
Antimony: Sb (ug/L) - TW	2011/01/10	< 0.02	No
Arsenic: As (ug/L) - TW	2011/01/10	0.2	No
Barium: Ba (ug/L) - TW	2011/01/10	21.6	No
Boron: B (ug/L) - TW	2011/01/10	14.00	No

Cadmium: Cd (ug/L) - TW	2011/01/10	< 0.003	No
Chromium: Cr (ug/L) - TW	2011/01/10	< 0.5	No
Lead: Pb (ug/L) – DW			
Mercury: Hg (ug/L) - TW	2011/01/10	< 0.020	No
Selenium: Se (ug/L) - TW	2011/01/10	< 1.0	No
Sodium: Na (mg/L) -	2012/01/16	5.72	No
Uranium: U (ug/L) - TW	2011/01/10	0.034	No
Fluoride: (mg/L) -	2012/01/16	0.17	No
Nitrite (mg/L) - TW	2014/01/20	< 0.003	No
Nitrite (mg/L) - TW	2014/04/14	< 0.003	No
Nitrite (mg/L) - TW	2014/07/14	< 0.003	No
Nitrite (mg/L) - TW	2014/10/20	< 0.003	No
Nitrate (mg/L) - TW	2014/01/20	< 0.006	No
Nitrate (mg/L) - TW	2014/04/14	< 0.006	No
Nitrate (mg/L) - TW	2014/07/14	0.006	No
Nitrate (mg/L) - TW	2014/10/20	< 0.006	No

Summary of Organic parameters sampled during this reporting period or most recent

Parameter	Sample Date	Result Value	Exceedance
Alachlor (ug/L) – TW	2011/01/10	< 0.02	No
Aldicarb (ug/L) – TW	2011/01/10	< 0.01	No
Aldrin + Dieldrin (ug/L) -	2011/01/10	< 0.01	No
Atrazine + N-dealkylated metabolites (ug/L) - TW	2011/01/10	< 0.01	No
Azinphos-methyl (ug/L) – TW	2011/01/10	< 0.02	No
Bendiocarb (ug/L) – TW	2011/01/10	< 0.01	No
Benzene (ug/L) – TW	2011/01/10	< 0.32	No
Benzo(a)pyrene (ug/L) – TW	2011/01/10	< 0.0040	No
Polychlorinated Bichenysl(PCB) (ug/L) – TW	2011/01/10	< 0.040	No
Prometryne (ug/L) – TW	2011/01/10	< 0.03	No
Bromoxynil (ug/L) – TW	2011/01/10	< 0.33	No
Carbaryl (ug/L) – TW	2011/01/10	< 0.01	No
Carbofuran (ug/L) - TW	2011/01/10	< 0.01	No
Carbon Tetrachloride (ug/L) - TW	2011/01/10	< 0.16	No

Chlordane:Total (ug/L) - TW	2011/01/10	< 0.01	No
Chlorpyrifos (ug/L) - TW	2011/01/10	< 0.02	No
Cyanazine (ug/L) - TW	2011/01/10	< 0.03	No
Diazinon (ug/L) - TW	2011/01/10	< 0.02	No
Dicamba (ug/L) - TW	2011/01/10	< 0.2	No
1,2-Dichlorobenzene (ug/L) - TW	2011/01/10	< 0.41	No
1,4-Dichlorobenzene (ug/L) - TW	2011/01/10	< 0.36	No
Dichlorodiphenyltrichloroethane(DDT) + metabolites (ug/L) - TW	2011/01/10	< 0.01	No
1,2-Dichloroethane (ug/L) - TW	2011/01/10	< 0.35	No
1,1-Dichloroethylene (ug/L) - TW	2011/01/10	< 0.33	No
Dichloromethane (ug/L) - TW	2011/01/10	< 0.35	No
2,4-Dichlorophenol (ug/L) - TW	2011/01/10	< 0.15	No
2,4-Dichlorophenoxy acetic acid (2,4-D) (ug/L) - TW	2011/01/10	< 0.19	No
Diclofop-methyl (ug/L) - TW	2011/01/10	< 0.40	No
Dimethoate (ug/L) - TW	2011/01/10	< 0.03	No
Dinoseb (ug/L) - TW	2011/01/10	< 0.36	No
Diquat (ug/L) - TW	2011/01/10	< 1.00	No
Diuron (ug/L) - TW	2011/01/10	< 0.03	No
Glyphosate (ug/L) - TW	2011/01/10	< 6.00	No
Heptachlor+Hepachlor Epoxide (ug/L) - TW	2011/01/10	< 0.01	No
Lindane: (ug/L) - TW	2011/01/10	< 0.01	No
Malathion (ug/L) - TW	2011/01/10	< 0.02	No
Methoxychlor (ug/L) - TW	2011/01/10	< 0.01	No
Metolachlor (ug/L) - TW	2011/01/10	< 0.01	No
Metribuzin (ug/L) - TW	2011/01/10	< 0.02	No
Monochlorobenzene (ug/L) - TW	2011/01/10	< 0.30	No
Paraquat (ug/L) - TW	2011/01/10	< 1.00	No
Parathion (ug/L) - TW	2011/01/10	< 0.02	No
Pentachlorophenol (ug/L) - TW	2011/01/10	< 0.15	No
Phorate (ug/L) - TW	2011/01/10	< 0.01	No
Picloram (ug/L) - TW	2011/01/10	< 0.25	No
Simazine (ug/L) - TW	2011/01/10	< 0.01	No
**THM (ug/L) - DW	2014	56.5	No

$ \begin{array}{c cccc} 10 & < 0.01 \\ \hline 10 & < 0.01 \\ \hline 10 & < 0.35 \end{array} $	ļ
	No
10 < 0.35	
10	No
10 < 0.14	No
10 < 0.01	No
10 < 0.43	No No
10 0.90	No
10 < 0.22	No No
10 < 0.02	No No
10 < 0.17	7 No
	$\begin{array}{cccc} (10) & < 0.35 \\ (10) & < 0.14 \\ (10) & < 0.01 \\ (10) & < 0.43 \\ (10) & < 0.22 \\ (10) & < 0.02 \\ (10) & < 0.17 \\ \end{array}$

^{**} Annual average (THMs)

List any Inorganic or Organic parameter(s) that exceeded half the standard prescribed in

Schedule 2 of Ontario Drinking Water Quality Standards.

Parameter	Result Value	Unit of Measure	Date of Sample
THM	55	Ug/L	2014/01/20
THM	56	Ug/L	2014/04/14
THM	66	Ug/L	2014/10/20

(Only if DWS category is large municipal residential, small municipal residential, large municipal non residential, small municipal non residential, large non municipal non residential)

Summary of lead testing under Schedule 15.1 during this reporting period

(applicable to the following drinking water systems; large municipal residential systems, small municipal residential systems, and non-municipal year-round residential systems)

Location Type	Number of Samples	Range of Lead Results (ug/L) (min#) – (max #)	Number of Exceedances
Distribution	0	N/A	N/A

^{***}The Huron Woods Drinking Water System has qualified for the plumbing exemption in Accordance with O. Reg. 170/03 schedule 15.1-5 (9) and (10). The next distribution lead sampling is scheduled for the winter sampling period of 2015.